




INTERNATIONAL OPERATIONS & MAINTENANCE CONFERENCE IN THE ARAB COUNTRIES

UNDER THE THEME

"MANAGING MAINTENANCE WITHIN INDUSTRY 4.0"
CONICIDE WITH THE 16TH ARAB MAINTENANCE EXHIBITION


Risk Assessment (RA) in Maintenance Activities - A specialized methodology through a simplified approach

GEORGE SCROUBELOS



The issue





Objective




The objective of this presentation is bi-fold:

- To present a Risk Assessment Study (RAS) for maintenance activities which will be as analytical as possible but also, easy to compile, use and update
- 2. To present several tools for recording the results in a user-friendly manner in the RAS Sheets




The Risk Assessment Methodology



The Risk Assessment Decision Focus





Hazard (Source) list (accidents - occupational diseases)



- 1. Floors
- 2. Hot/ cold objects
- 3. Chemicals
- 4. Machinery
- 5. Tools (hand, power)
- 6. Equipment
- Network lines (cabling, piping, ducts etc.)
- 8. Installations
- 9. Structural installations
- 10. Vehicles

- 11. <u>Loads</u>
- 12. Confined Spaces
- 13. Low density materials
- 14. Pests, animals, rodents
- 15. Microorganisms
- 16. Microclimate
- 17. Workplace organization
- 18. Work organization (psychosocial)
- Combustibles + ignition sources
- 20. Behavior

Danger list (accidents - occupational diseases)



- 1. Slipperiness
- Obstruction of movement
- 3. Height difference
- 4. <u>Temperature</u> extremes
- 5. Reactivity
- 6. Movement/Inertia
- 7. Sharpness (edge/point)
- 8. Particle release
- 9. Tension (belt/ spring)
- 10. Weight

- 11. Pressure
- 12. Vacuum
- 13. <u>Noise</u>
- 14. Poor visibility
- 15. Radiation
- 16. Electrical voltage
- Asphyxiating atmosphere (lack of O₂/ toxic substances presence)
- 18. <u>Humidity</u>
- Insufficient ventilation
- 20. Infectiousness

- 21. Low density
- 22. Poor illumination
- 23. Air draught
- 24. Vibration
- 25. <u>Sedentary/ static</u> work
- 26. Monotony
- 27. Stressfulness
- 28. <u>Intensiveness</u>
- 29. Storage height
- 30. Center of gravity position

Probable Incident Scenario list


(maximum 17)



- 1. Slipping at (& falling at/ to/ from)
- Tripping/ stumbling at (& falling at/ to/ from)
- Bumping/ knocking/ hitting into/ against (protruding) objects/ surfaces at the same level
- Hit/ struck/ crushed by falling/ moving objects
- 5. Falling from another level
- Contact with elements under voltage
- Contact of the skin/ eyes with sharp/pointed objects
- 8. Contact of the skin/ eyes with hot/ cold surfaces/ chemicals
- 9. <u>Inhalation of chemicals</u>

- 10. Swallowing of objects/ chemicals
- 11. Exposure to biohazards
- 12. Fire
- 13. Explosion
- Entrapment/ asphyxiation by low density/ asphyxiant materials
- 15. Overexertion
- Exposure to adverse working environment (microclimate, physicochemical agents)
- Working under adverse psychosocial conditions

Risk Assessment Study (The 10-step process)



Risk Assessment Measures Category List




RISK ASSESSMENT MEASURES Issue date: Document No.: Revision:	Page 1 / 1
---	------------

LEGISLATION	H&S Legislation						
SPECIFICATIONS	EN, ISO, Corporate						
H&S SYSTEM (Procedures/ Guidelines/ Work	BS OHSAS 18001:2007, ISO 45001:2018						
Instructions/ Safe Methods of Works)							
COMMUNICATION (Training, Meetings, Promotional Activities)	General Safety Rules Fire Safety – Emergency Planning – Evacuation Procedures PPE Ergonomics/ Manual Handling Safe Chemicals Management Safe Use of Lifting Equipment Machine Safety/ LOTOTO Stress Working at Heights	Safety Booklets Safety Posters Safety Meetings Toolbox Talks Chemical Safety Cards Incompatibility Charts					
PERSONAL PROTECTIVE EQUIPMENT	Work Clothes, Isothermal Jackets Safety Shoes Safety Glasses, Goggles, Face Shields Ear Muffs, Plugs	Dust Masks, Welding Masks, Half or Full- Face Masks, Breathing Apparatus Safety Gloves for Sharps, Chemicals, Heat, Cold					
SIGNAGE	Prohibition Obligatory Hazard Evacuation	Fire Safety Informative Descriptive					
SAFETY EQUIPMENT	Safety Mirrors Eye wash	Body Showers Spill Materials					
MEASUREMENTS	Illumination Thermal Comfort Noise	Dust Chemical Substances Radiation					

Risk Assessment Sheet Example per Area

(valid for all works performed in the area)



^{*} S:SEVERITY (1-10) L:LIKELIHOOD (1-10) F:FREQUENCY (1-10) R:RISK (SXLXF=1-1000)

Risk Assessment Example per Area

(valid for all works performed in the area)

Text		F	RISK ASSESSM	IENT (R.A	A.) SHEET	ISSUE DATE : DOCUMENT No : REVISION :	PAGE 1/6					
7 to 60 (1)	AREA: Maintenance Shop			R.A. TEAM:	la la dia Assa	•						
	JOB : All jobs in the Area	TCATION		TASK : All tas		UTIONS / MEASURES						
FREE DESIGNATION AND ADDRESS OF THE PARTY OF	RISK IDENTIF POTENTIAL INCIDENT SCENARIA (brief descriptio		EXPOSED / AFFECTED			PRECAUTIONS / MEASURES EXISTING (E)						
	scenario including the danger sources and associate	ed hazards)	PERSONNEL		RECOMMENDED (R)							
	OBSTRUCTION OF MOVEMENT Slipping, tripping, falling while moving in the area due to poor housekeeping loose floor cabling	Maintenance Technicians Mintenance Technicians Maintenance Technicians Mintenance Technicians Mint										
	PHOTOGRAPH		HEALTH EFFECT	COMMUNICATION EM: Tool Safety, M	ON (meetings/training/promotion Machine Shop Safety, Housekee	onal activities etc.): ping Rules						
			 Contusion Fracture Concussion Sprain Strain Cut 	RM: Floor trunks, EM: First Aid lit MEASUREMENT: GENERAL RULE: RM: Do not aband RM: Store perman accordingly RM: All tools shou RM: All tools cabli RM: All spare part shelves	S: lon or stack spare parts, tools in lent hardware (equipment, was lid be stored in place when not i ling should be either taped or ro loses should be maintained in pla ts and unfinished machine part	n pathways te bins etc.) at specified places and mark in use outed in trunks, or overhead ace when not in use s should kept on the working benches or						
					to Hammer / Fine (*)							
		S	F	L	$\mathbf{R} = \mathbf{S} \times \mathbf{L} \times \mathbf{F}$	ACTION PLAN PRIOR	RITY					
	EXISTING SITUATION											
	AFTER MEASURES IMPLEMENTATION											

Maintenance Activities in Phases



Preparation

Infrastructure works management

- Target (machinery, equipment, building, installations etc.)
- Procedures, guidelines
- Hardware (tools, chemicals, PPE, LOTOTO, spare parts etc.)
- Maintenance area preparation (evacuation, traffic control, signage etc.)
- Maintenance target (machinery, equipment, installation, building etc.)

Execution

"Core" maintenance works

- Procedures, guidelines Implementation
- Power supply management → LOTOTO, Confined space entry
- Hardware use for repair → Hand & power Tools, Devices
- Repair, replacement of worn parts
- Disassembly, reassembly → Special tasks

Delivery

Trial runs, commissioning, restoration

- Procedures, guidelines Implementation
- Hardware use
- Commissioning (test/ trial runs)
- Area & object restoration (housekeeping, waste management)
- Delivery to users

Maintenance Works Special Characteristics





Maintenance works

- Lack of housekeeping
- Mentally & physically demanding activities
- Specialized knowhow
- Task complexity
- Repeated tasks
- "Non-productive" work




Maintenance personnel


- Moves in all areas
- Move outside the premises
- They are potentially involved in all installations & equipment
- They believe that since they are usually highly skilled they possess the knowhow to execute their works safely

Maintenance Activities (MAs) Risk Combination (Risk Analysis)











Risk Assessment Methodology Process


(Specifications)



Risk Assessment Process Stages




Risk Assessment Sheet Example per Hazard Source



Risk Assessment Sheet Example per Hazard Source

(valid for all works performed using the Hazard Source)





RISK ASSESSMENT SHEET PER MACHINERY OR EQUIPMENT








Machinery/ Equipment Code: BAKERY BACKTECH Operation BUN PRODUCER Code number ZRB0003148 Issue date Assessors







	y/ E ode	quipment
Area	:	BAKERY
Machine type	:	BACKTECH
Operation	:	BUN PRODUCER
Code number	. :	ZRB0003148
Issue date	. :	
Assessors	:	

ADDITIONAL INFORMATION



MOVING PARTS - SHARPNESS

. EM: Machine guarding should be regularly checked for integrity



· PM: Post signs on all machine guards (A19)




. PM: All interlock switched should be regularly checked

. EM: Approved emergency stops are installed throughout the production line.

. PM: Extend the existing guards at the machine exit.

Risk Assessment Sheet Example per Task


(valid for all Jobs conducted by all Specialties)



Simplified RA Methodology for Maintenance








The Line of Thinking & The Principle




- The Maintenance Activities (MA) Risk Assessment Study (RAS) must specify preventive measures for all Tasks performed → JSA
- Maintenance Job Tasks are usually more than 1000
- However, the Probable Incident Scenarios (PIS's) are of limited number (maximum 17)
- Some PIS's are already identified during the previous Risk Assessment
 Stages and need not be repeated for each Task
- Therefore, one can develop a RAS not per Task but per PIS which would include all applicable Job Tasks of each specialty excluding the scenarios already identified in the General RAS.

Risk Assessment Study




(valid for all Job Tasks)



		N (SPECIALTY) IT STUDY PER JOB	Issue Date : Document No. : Revision :	Page 1 / 19
JOB-POSITION:			ASSESSORS :	
JOB-POSITION STEP-ANALYSIS INT	TO JOBS (Duties):			
1.		11.		
2.		12.		
3.		13.		
4.		14.		
5.		15.		
6.		16.		
7.		17.		
8.		18.		
9.		19.		
10.		20.		
		l		

 The initial form the Maintenance Professionals must fill and deliver to the H&S Risk Assessor for the latter to initiate the MAs JSA

(valid for all Job Tasks)



Page

2 / 20

AFTER

(valid for all Job Tasks)



RISK	ASSESSMENT	CTIIDV	DED IOR

Issue Date :
Document No. :
Revision :

ASSESSORS :

Page 1 / 13

SPECIALTY: Maintenance

JOB ANALYSIS:

- Contact with the Production Supervisor (for the machinery working status)
- 2. Contact with the Machine Operators (for malfunctions)
- 3. Daily visual machinery inspection
- 4. Machine failures Repair & Maintenance
- 5. Semesterly maintenance of all machinery
- Working at heights
- 7. Forklift operation
- 8. Overhead crane operation
- 9. Grinding machine operation
- 10. Machine-tool operation (boring)
- 11. Machine-tool operation (lathe, drill, mill)
- 12. Diesel engine basic maintenance
- 13. Hand pallet truck operation
- 14. Air-conditioning filter change

- 15. Cooperation with electricians (e.g. when repairing a motor)
- 16. Visiting the warehouse to get chemicals
- 17. Use of chemicals on chillers and the production machines
- 18. Roller conveyor cleaning
- Welding
- 20. Repair and maintenance of pressurized air and hydraulic systems
- 21. Use of pressurized air
- 22. Office work Computer usage
- 23. Contacting suppliers
- 24. SAP use
- Contacting machine shops
- 26. Contractor supervision
- 27. Visiting all plant areas
- 28. Moving to and from the working area

ш	Task	HAZARD SOURCE/ DANGER /	HEALTH	H&S CORRECTIVE MEASURES		R	ISK F	ACTO	R	
Н	Serial	•			В	EFOR	E		AFTER	2
Ш	No.	POTENTIAL INCIDENT SCENARIO	TENTIAL INCIDENT SCENARIO CONSEQUENCES EXISTING (E) / RECOMMENDED (R)		S	F	L	S	F	L
•	IN	Exposure to Voltage Exposure to Noise Slipping, Tripping, Falling from Stairs Slipping, Tripping, Falling on the Floor		See General Area Risk Assessment						
	o	Fire Overhead weights Manual handling Ergonomic Infectious agents								

^{&#}x27;S: SEVERITY (1-10) L: LIKELIHOOD (1-10) F: FREQUENCY (1-10) R: RISK FACTOR (SxLxF=1-1000)
"O": The risk concerns ALL jobs performed by the job position, "IN" The risk concerns the installation/ premises/ area infrastructure

(valid for all Job Tasks)



RISK ASSESSMENT STUDY PER JOB

Issue Date : Document No. Revision :

Page 3 / 13

Task Serial No.	HAZARD SOURCE/ DANGER /	HEALTH	LING CORRECTIVE MEAGURES		R	ISK F	АСТО	R		
ш		PROBABLE INCIDENT	CONSEQUEN	CONSEQUEN H&S CORRECTIVE MEASURES	В	EFOR	E	-	AFTER	Ł
Н	No.	SCENARIO	CES	EXISTING (E) / RECOMMENDED (R)	S	F	L	S	F	L
	IN	SLIPPERINESS Slipping and falling on the floor and potentially fall on hard surfaces, due to Chemical spillage Metal welding residues Lubricants spillage Cleaning agents/ water Tools on the floor Metal machine-tools residues On-the-floor loose temporary cabling Slippery material transferred on the Safety Shoe soles Materials placed on the floor (e.g. packaging materials)	Fracture Concussion Sprain Strain Contusion Cut Brazing	EM General Housekeeping Rules EM Housekeeping procedures/ guidelines EM General Safety Rules training EM Use of anti-slip safety shoes RM Industrial vacuum cleaner RM Emergency Spill Kits including Disposal EquiRMent RM Industrial vacuum cleaner RM Anti-slip floor material EM Regular floor cleaning RM Do not abandon spare parts, loose cables, tools and other objects on the floor	8	200		8	4	
	0	Infectious AGENTS Infection due to poor personal hygiene Possible contact with rodents, reptiles, insects Illness due to travel to foreign countries	Death Come Poisoning Infection Contusion Abrasion Illness	EM Annual pest control program EM Annual examination by an Occupational Physician RM The consumption of F&B is strictly prohibited in the working areas RM All personnel must follow high hygiene standards RM All F&B Must be consumed and refreshed daily RM All personnel travelling abroad should be informed and follow the	10	160		10	90	3

^{*}S: SEVERITY (1-10) L: LIKELIHOOD (1-10) F: FREQUENCY (1-10) R: RISK FACTOR (SxLxF=1-1000)

[&]quot;O": The risk concerns ALL jobs performed by the job position, "IN" The risk concerns the installation/ premises/ area infrastructure

(valid for all Job Tasks)



Task	k HAZARD SOURCE/ DANGER /	HAZARD SOURCE/ DANGER /		LIEALTII	US CORRECTIVE MEACURES		R	ISK F	ACTO	R	
Serial	PROBABLE INCIDENT	HEALTH CONSEQUENCES	H&S CORRECTIVE MEASURES EXISTING (E) / RECOMMENDED (R)	В	EFOR	E		AFTER	1		
No.	SCENARIO	CONSEQUENCES		S	F	L	S	F	L		
3 5 7 11 12 16 17 18 20	REACTIVITY Inhalation of fumes or skin contact (cleaning agents, lubricants, solvents): During equiRMent and machinery R&M During spare part surface cleaning, degreasing During the use of adhesives Because of probable chemical spillage Due to violating safety rules Inhalation of fugitive emissions during sand/ glass blasting in case of extraction system failure or during the feeding of the sand to the sand blaster Exposure (inhalation, skin, eye) to welding fumes Exposure (inhalation) to airborne particles (dust, trimmings, flings) during material cutting, brazing	Irritation (skin, eye) Bum Poisoning Respiratory problems Loss of consciousness Long-term health effects	Legislation / specifications EM Chemical agents safe handling EM CLP/ GHS EM SDS EM Health Program Procedures/ guidelines RM Safe chemical handling/ storage RM Spill control emergency procedures PM Spill control equiRMent RM Training RM Health Examinations for Fit-to-the Job Certificates Communications RM Chemical safety cards RM Toolbox Talks RM Chemical Substances Committee meetings RM Safety Chemicals Handing Booklet Signage EM FIGURE FOR STORE F	9	225	5	9	180	4		

*S: SEVERITY (1-10) L: LIKELIHOOD (1-10) F: FREQUENCY (1-10) R: RISK FACTOR (SxLxF=1-1000)

"O": The risk concerns ALL jobs performed by the job position, "IN" The risk concerns the installation/ premises/ area infrastructure

(valid for all Job Tasks)



RISK ASSESSMENT STUDY PER JOB

Issue Date : Document No. Revision :

Page 10 / 13

Task	HAZARD SOURCE/ DANGER /	HEALTH	H&S CORRECTIVE MEASURES		RISK FACTOR BEFORE BEFOR				
Serial	INCIDENT	CONSEQUEN	EXISTING (E) / RECOMMENDED (R)			E		EFOR	E
No.	Interpetiti	CES	Examine (E) / RECOMMENDED (R)	S	F	L	S	F	L
4 6 7 8 16	ΗΟΤ SURFACES Κίνδυνος έκθεσης στις θερμές επιφάνειες του μηχανολογικού εξοπλισμού κατά τη διάρκεια μικ ροεπεμβάσεων Κίνδυνος έκθεσης σε θερμό υλικό κατά τη συνήθη εργασία ή κατά την εκτέλεση εργασιών σε παράπλευρα σημεία του μηχανολογικού εξοπλισμού Κίνδυνος επαφής με θερμές επιφάνειες εξοπλισμού, θερμές κατεργασμένες επιφάνειες μετά από συγκολλήσεις ή με γυμνή φλόγα	• Έγκαυμα • Άλλος τραυματισμός/ βραχυχρόνια επίπτωση	ΥΜ Υποχρεωτική χρήση θερμάντοχων γαντιών ασφαλείας και γυαλιών προστασίας κατά τη διάρκεια θερμών κολλήσεων ΥΜ Υποχρεωτική χρήση ρουχισμού ασφαλείας κατά τις κολλήσεις ΠΜ Τοποθέτηση πυρίμαχου παραπετάσματος για τις συγκολλήσεις ΠΜ Χρήση ποδιάς και μάσκας για συγκολλήσεις Επισήμανση όλων των θερμών σημείων του μηχανολογικού εξοπλισμού ΠΜ Υποχρεωτική χρήση γαντιών ασφαλείας για επαφή με θερμές επιφάνειες	7	210	5	7	140	4
2 3 4 5 7 9 15	PARTICLE RELEASE Κίνδυνος τραυματισμού από την εκτόξευση σωματιδίων, όπως: - γρεζιών, ρινισμάτων κατά τις εργασίες επεξεργασίας μετάλλων /κατά τον καθαρισμό των μηχανημάτων με πεπιεσμένο αέρα ή αν μαγκώσει ο τροχός ή άλλες εργαλειομηχανές - σπινθήρων κατά τις εργασίες κολλήσεων - λεπίδων και σωματιδίων από τα πριόνια	Τομή Μωλωπισμός- Κάκωση Αμυχή-Εκδορά Τύφλωση Έγκαυμα Άλλος πραυματισμός	ΥΜ Υποχρεωτική χρήση γυαλιών ασφαλείας σε όλες τις εργασίες επεξεργασία μετάλλων ΥΜ Υποχρεωτική χρήση γυαλιών προστασίας και ρουχισμού ασφαλείας κατά τις κολλήσες ΥΜ Τα μηχανήματα - εξοπλισμός διαθέτουν πιστοποίηση CE (επέκταση του μέτρου όπου απαπείται) ΠΜ Τοποθέτηση πυρίμαχου παραπετάσματος για τους σπινθήρες ΠΜ Πλύντης ματιάν ή ΚΙΤ φυσιολογικού ορού στο φαρμακείο του τμήματος ΤΜ Χρήση ποδιάς και μάσκας συγκόλλησης κατά τις κολλήσεις ΠΜ Να τοποθετηθούν ΠΣΑ σε όλα τα κινητά μέρη των εργαλειομηχανών ΠΜ Απαγορεύεται η παραβίσση ή παράκαμψη των ΠΣΑ των εργαλειομηχανών ΠΜ Κατά τη χρήση των πριονιών ή άλλων κοπτικών εργαλείων να γίνεται χρήση γυαλιών προστασίας και να τοποθετηθεί κατάλληλη σήμανση ΠΜ Κατά τον καθαρισμό των εργαλειομηχανών από τα γρέζια και ρινίσματα να μην χρησιμοποιείται ο πεπιεσμένος αέρας αλλά η σκούπα αναρρόφησης και ο εργαζόμενος να φοράει τα γυαλιά προστασίας			128	4		
4	RADIATION Έκθεση σε ακτινοβολία κατά τη διάρκεια των κολλήσεων	Τύφλωση Αναπνευστικές διαταραχές	ΥΜ Οι συγκολλήσεις να εκτελούνται από αδειοδοτημένους συγκολλητές ΥΜ Υποχρεωτική η χρήση των ΜΑΠ προστασίας οφθαλμών κατά τη διάρκεια των συγκολλήσεων ΠΜ Τοποθέτηση πυρίμαχου παραπετάσματος για τους σπινθήρες	9	9 5 5		9	4	3
		 Λιποθυμἷα Υποβάθμιση όρασης 	 ΠΜ Να γίνεται τακτική χρήση του παραπετάσματος προστασίας από την ακτινοβολία, κατά την διάρκεια εκτέλεσης εργασιών κόλλησης ΠΜ Δημιουργία σταθερών θέσεων συγκόλλησης και κατασκευή συστημάτων απαγωγής των αερίων 		225			108	

*S: SEVERITY (1-10) L: LIKELIHOOD (1-10) F: FREQUENCY (1-10) R: RISK FACTOR (SxLxF=1-1000)

"O": The risk concerns ALL jobs performed by the job position, "IN" The risk concerns the installation/ premises/ area infrastructure

(valid for all Job Tasks)

RISK ASSESSMENT STUDY PER JOB

Issue Date : Document No. Revision :

Page 4 / 13

Task Serial	HAZARD SOURCE/ DANGER / PROBABLE INCIDENT	HEALTH CONSEQUEN	H&S CORRECTIVE MEASURES	В	R EFOR			ACTOR					
No.	SCENARIO	CES	EXISTING (E) / RECOMMENDED (R)	s	F	L	S	F	L				
IN	OBSTRUCTION TO MOVEMENT Tripping against obstades due to: • Materials, tools, cable trunks, wheeled carts, stored materials, pallets etc. • Floor uneven surfaces (steps, holes) • Machinery & equipment supports with possible fall on the floor and bumping against hard surfaces.	Death Coma Concussion Fracture Dislocation Swelling Bruising	EM Use of safety shoes EM Floor demarcation of the welding pressurized bottles EM Floor demarcation of the machinery & equipment EM Storage of objects and loads away of circulation areas EM Housekeeping EM Immediate removal of tools after a maintenance task is completed RM Immediate removal of flexible hoses and cables after use RM Exercise caution during moving in the various areas RM Report all holes and degraded floor surfaces to your Supervisor or the H&S Professional RM Remove all materials not regularly used RM Flexible hoses when not in use should be rolled around reels		240		-,-,-				8	128	4
4 5 6 9 10 11 12 14 15 18 19 20	HAND TOOLS Injury due to hand tools misuse	Puncture Cut Bruising Contusion Abrasion Ergonomic problems	EM PPE use (gloves, safety glasses) EM All tools must be checked prior to their use EM All tools must be certified and suitable for professional use; no self- made tools are allowed RM All tools must be used for the purpose they were made for RM Place all tools in their tool-case or their dedicated place after use RM Use ergonomic tools and safety cutters	6	216	6	6	180	5				

^{*}S: SEVERITY (1-10) L: LIKELIHOOD (1-10) F: FREQUENCY (1-10) R: RISK FACTOR (SxLxF=1-1000)

[&]quot;O": The risk concerns ALL jobs performed by the job position, "IN" The risk concerns the installation/ premises/ area infrastructure

(valid for all Job Tasks)

RISK ASSESSMENT STUDY PER JOB

Issue Date : Document No. Revision :


Page 6 / 13

Task	HAZARD COURCE / DANCER /	HEALTH	HOC CORRECTIVE MEACURES		R	ISK F	ACTO	R				
Serial	HAZARD SOURCE/ DANGER / INCIDENT	CONSEQUENC	H&S CORRECTIVE MEASURES EXISTING (E) / RECOMMENDED (R)	В	EFOR	E	E	BEFOR	RE			
No.	INCIDENT	ES		S	F	L	S	F	L			
O	ΙΝΤΕΝSIVE WORK – MANUAL HANDLING Σωματική καταπόνηση λόγω πολύωρης εντατικής ορθοστατικής και καθιστικής εργασίας Σωματική καταπόνηση λόγω διαρκούς μετακίνησης προς και από τη θέση εργασίας Σωματική καταπόνηση λόγω αφύσικης στάσης σώματος (σκύψιμο, κάμψη, στρέψη κορμού) Κίνδυνος τραυματισμού μέσης κατά την χειρωνακτική διακίνηση φορτίων Υπερπροσπάθεια κατά την άρση και μεταφορά φορτίων μεγάλου βάρους	 Μυσσκελετικά προβλήματα Κεφαλαλγία Ψυχικές διαταραχές Νευρικές διαταραχές Άγχος Άλλη μακροπρόθεσμη επίπτωση 	ΥΜ Χρήση υποδημάτων ασφαλείας ΥΜ Χρησιμοποιούνται τα κατάλληλα μέσα διακίνησης φορτίων, χρήση παλετοφόρων, παλετοκάροτσων και παλάγκου ΥΜ Καρότσια μεταφοράς φιαλών ΥΜ Βαριά αντικείμενα Β> 25 kgr να μετακινούνται με την χρήση μηχανικής υποβοήθησης ή με περισσότερους από έναν εργαζομένους ΠΜ Η στάση του αώματος κατά την εκτέλεση χειρονακτικής μεταφοράς φορτίου πρέπει να είναι : ίσια πλάτη, λυγισμένα πόδια, ποτέ σκυφτή μέση και το φορτίο όσο το δυνατό πιο κοντά στον κορμό του σώματος, να κοιτά μπροστά και να μην σκύβει το κεφάλι ΠΜ Ο εργαζόμενος πρέπει πάντα να ελέγχει την διαδρομή από πριν, για τον εντοπισμό και αποφυγή παγίδων κατά την μεταφορά φορτίου. Ένα βαρύ φορτίο πρέπει να κραπέται κάθετα πάνω από το κέντρο βάρος του ΠΜ Διαλλείματα σε περίπτωσης κόπωσης ΠΜ Τάπητας αντικραδασμικός, στο σημείο όπου πραγματοποιείται στατική ορθοστατική εργασία ΠΜ Να αντικατασταθούν τα σκαμπό που δεν είναι κατάλληλα από το χώρο. Να τοποθετηθούν κατάλληλα καθίσματα.		288					8	160	4
			ΥΜ Χρήση ΜΑΠ (γάντια προστασίας) σε όλες τις εργασίες επαφής με	9	5	6	9	4	5			
0	SHARPNESS (POINT / EDGE) Πρόκληση ατυχήματος από: αιχμηρές επιφάνειες μετάλλων, εξαρτημάτων και επεξεργαζόμενων υλικών αιχμηρές επιφάνειες υπολεμμάτων εργασιών (ρινίσματα - γρέζια) αιχμηρές επιφάνειες κατά το μοντάρισμα μηχανών, προστατευτικών συστημάτων ασφαλείας κ.α. προεξέχοντα τμήματα εξοπλισμού το χειρισμό εργαλείων τη χρήση πριονιών	 Τομή Αμυχή-εκδορά Τύφλωση 	αιχμηρές επιφάνειες ΥΜ Καθαρισμός εργαλειομηχανών από γρέζια - ρινίσματα μετά το πέρας των εργασιών ΥΜ Αντικατάσταση των ΜΑΠ (γάντια) σε περίπτωση φθοράς τους ΥΜ Όλα τα εργαλεία είναι πιστοποιημένα κατά CE. Επέκταση του μέτρου ΥΜ Εκπαίδευση του προσωπικού για τη χρήση των πριονιών ΠΜ Στα προεξέχοντα τμήματα του εξοπλισμού να τοποθετούνται προστατευπικές διατάξεις και να επισημαίνονται κατάλληλα ΠΜ Κατά την αλλαγή των εξαρπημάτων των μηχανών ο χειριστής να φοράει πάντιστε γάντια εργασίας ΠΜ Κατά τη χρήση των πριονιών ή άλλων κοπτικών εργαλείων να γίνεται χρήση γυαλιών προστασίας και γαντιών με αντοχή στη διάτρηση και να τοποθετηθεί κατάλληλη σήμανση ΠΜ Κατά τις εργασίες με εργαλεία χερός να γίνεται χρήση γαντιών ασφαλείας ΠΜ Να γίνεται χρήση κοπιδιών ασφαλείας ΠΜ Να τοποθετηθούν ΠΣΑ σε όλα τα κινούμενα μέρη των πριονιών (η διαδικασία έχει ήδη ξεκινήσει)		270			180				

*S: SEVERITY (1-10) L: LIKELIHOOD (1-10) F: FREQUENCY (1-10) R: RISK FACTOR (SxLxF=1-1000)


"O": The risk concerns ALL jobs performed by the job position, "IN" The risk concerns the installation/ premises/ area infrastructure

(valid for all Job Tasks)



OMAINTEC 32

(valid for all Job Tasks)




"O": The risk concerns ALL jobs performed by the job position, "IN" The risk concerns the installation/ premises/ area infrastructure

Total Risk Assessment Study



Number of RA Sheets = few 1000ands (Avg.=13500)



- Working hours saved → approximately 250/ RA Study
- This methodology has been implemented in the heavy industry (metal processing, plastics, food)

The simplicity of the updating process




If a job/ task is added, removed, changed, then ...

- 1. Change the job/ task list
- 2. Add/ remove the incident scenario task list box
- 3. Update the data only in the applicable fields

	·	3. Upda	te the data only in the applicable field	45					
ask erial No.	HAZARD SOURCE/ DANGER / INCIDENT	PALIH	H&S CORRECTIVE MEASURES EXISTING (E) / RECOMMENDED (R)	KISK FACTOR					
		CONSEQUEN		BEFORE			BEFORE		
				S	F	L	S	F	L
4 6 8 8	• Κίνδυνος έκθεσης στις θερμές επικάνειες του μηχανολογικού εξορικομού ματά τη διάρκεια μικροεπεμβάσεων • Κίνδυνος έκθεσης σελιθερμό υλυτό κατά τη συνήθη εργασία η κατά τη εκτέλεση εργασιών σε μαράπλευρα σημεία του μηχανολογικού εξοπλισμού • Κίνδυνος εναφής με θερμές επιφάνειες εξοπλισμού, θερμές κατεργασμένες επιφάνειες μετά από συγκολλήσεις ή με	 Εγκαυμα λλος η αυματισμός/ βλαχυχρόνια ετι Υωση 	ΥΜ Υποχρεωτική χρήση θερμάντο. Υ γαντιών ασφαλείας και γυαλιών προστασίας κατά τη διάρκεια θερμών κολλήσεων ΥΜ Υποχρεωτική χρήση ρουχισμού ασφαλείας κατά τις κολλήσεις ΠΜ Τοποθέτηση πυρίμαχου παραπετάσματος για τις συγκαλλήσεις ΤΑ Χρήση ποδίας και μάσκας για συγκολλήσεις Επισήμανση άλων των θερμών σημείων του μηχανολογικού εξοπλισμού ΤΜ Υποχρεωτική χρήση γαντιών ασφαλείας για επαφή με θερμές επιφάνειες	7	210	5	7 5		4
	γυμνη φλόγα		ΥΜ Υποχρεωτική χρήση γυαλιών ασφαλείας σε όλες τις εργασίες	8	6	5	8	4	4
2 3 4 5 9 15 16	PARTICLE RELEASE Κίνδυνος τραυματισμού από την εκτόξευση σωματιδίων, όπως: γρεξιών, ρινισμάτων κατά τις εργασίες επεξεργασίας μετάλλων /κατά τον καθαρισμό των μηχανημάτων με πεπιεσμένο αέρα ή αν μαγκώσει ο τροχός ή άλλες εργαλειομηχανές σπινθήρων κατά τις εργασίες κολλήσεων λεπίδων και σωματιδίων από τα πριάνια	 Τομή Μωλωπισμός- Κάκωση Αμυχή-Εκδορά Τύφλωση Έγκαυμα Άλλος πραυματισμός 	επεξεργασία μετάλλων Υποχρεωτική χρήση γυαλιών προστασίας και ρουχισμού ασφαλείας κατά τις κολλήσες Υπου μέτρου όπου απαπείται) Ππουθετηση πυρίμαχου παραπετάσματος για τους απινθήρες Ππου μέτρου όπου απαπείται) Ππουθετηση πυρίμαχου παραπετάσματος για τους απινθήρες Ππουθετηση πυρίμαχου παραπετάσματος για τους απινθήρες Ππουθετηση ματών ή ΚΙΤ φυσιολογικού ορού στο φαρμακείο του τμήματος Ππουθετηθούν ΠΣΑ σε όλα τα κινητά μέρη των εργαλειομηχανών Ππουθετηθούν ΠΣΑ σε όλα τα κινητά μέρη των εργαλειομηχανών Ππουθετηθούν ΠΣΑ σε όλα τα κινητά μέρη των εργαλειομηχανών Ππουθετηθούν παραβίσση ή παράκαμψη των ΠΣΑ των εργαλειομηχανών Ππουθετηθούν που πριονιών ή άλλων κοπτικών εργαλείων να γίνεται χρήση γυαλιών προστασίας και να τοποθετηθεί κατάλληλη σήμανση Ππουθετηση των καθαρισμό των εργαλειομηχανών από τα γρέξια και ρινίσματα να μην χρησιμοποιείται ο πεπιεσμένος αέρας αλλά η σκούπα αναρρόφησης και ο εργαζόμενος να φοράει τα γυαλιά προστασίας	240			128		
4	RADIATION Έκθεση σε ακτινοβολία κατά τη διάρκεια των κολλήσεων	 Τύφλωση Αναπνευστικές δισταραχές Αιποθυμία Υποβάθμιση όρασης 	 ΥΜ Οι συγκολλήσεις να εκτελούνται από αδαιοδοτημένους συγκολλητές ΥΜ Υποχρεωτική η χρήση των ΜΑΠ προστασίας οφθαλμών κατά τη διάρκεια των συγκολλήσεων ΠΜ Τοποθέτηση πυρίμαχου παραπετάσματος για τους σπινθήρες ΠΜ Να γίνεται τακτική χρήση του παραπετάσματος προστασίας από την ακτινοβολία, κατά την διάρκεια εκτέλεσης εργασιών κόλλησης ΠΜ Δημιουργία σταθερών θέσεων συγκόλλησης και κατασκευή συστημάτων απαγωγής των αερίων 	225			108		

Conclusions









Dr George Scroubelos

- General Manager, RMS SPPCC
- Chairman, EFNMS HSE Committee



27 Sorou str.

151 25 Maroussi

Greece

Tel.: +30 210 6149963

Fax: +30 210 0080867

Mob: +30 6972 011000

E-mail: gs-rms@otenet.gr

